



MFAGA

Adaptor, smooth increased (for negative pressure only)

Übergangsstück, glatt erweitert (ausschließlich Unterdruck)

Raccord simple paroi, lisse augmenté (uniquement pour dépression)

Aansluitstuk, glad vergroot (uitsluitend voor onderdruk)



\emptyset	130	150	180	200
A	135	155	185	205